

Date of Risk Assessment:	1 May 2026	1/2
---------------------------------	------------	-----

38 Windyridge, Bisley, Stroud, GL6 7DA
 Website: <https://www.astralsound.com>

Telephone: +44(0)1452 770042

On Site: +44(0)7773 697309
 email: info@astralsound.com

Assessed By:	Tony Lloyd
---------------------	------------

Client:	General Policy
----------------	----------------

Location:	Workshop
------------------	----------

Hazard	Potential Harm	Hazard Rating (0-6)	Likelihood (0-6)	Measures in Place	Further Action	By Whom	When
Moving vehicles on site	Injury from impact or crushing	4	2-3	Reverse sensors	Slow movement on site, supervision and hazard lights where appropriate	TL	On site access/egress
Handling Equipment	Injury from lifting or crush injury from dropping	3	2-4	Wheelboards and ramps, gloves, training and supervision of staff and volunteers	Minimise distances for carrying, shared lifting of heavy items	TL, Staff or volunteers	Loading, unloading or moving equipment
Stacked equipment	Injury from lifting or dropping equipment.	1-2	2-3	Supervision of staff and volunteers	Shared lifting of heavy items	TL, staff or volunteers	On stacking or unstacking equipment
	Injury from stack toppling			Equipment stacked securely		TL, staff or volunteers	Whenever equipment is stacked
230V portable equipment	Shock/ electrocution	5	1	Routine inspection, testing and maintenance of equipment	RCD/RCCBO devices at all mains supply points	TL	On use and on schedule
Cleaning liquids, paint, adhesives, solvents and sprays	Injury or loss of consciousness from inhalation of fumes	4	2	Liquids kept in sealed containers	Ventilate workspace when in use	TL	On storage and use
	Damage to eyes or skin from contact	3	3	Vinyl gloves and safety goggles available	Ensure use of PPE when required	TL	On use
	Bonding of skin by adhesive	2	2	Acetone readily accessible	Care/supervision when using adhesives	TL	On use

